No new data available Fri Aug 9 14:19:25 2002

Coordinate System: 121F03 Sensor ID: 121-f03 ; Axis: Sum of XYZ ; Windowing Method: Hanning

Cutoff Frequency in Hz: 200 df in Hz: 0.2441 Samples per sec: 500.0 PSD Points: 2048 Overlap in %: 0 Temporal Resolution in sec: 4.096



No new data available Fri Aug 9 14:19:48 2002

Coordinate System: 121F04 Sensor ID: 121-f04 ; Axis: Sum of XYZ ; Windowing Method: Hanning

Cutoff Frequency in Hz: 200 df in Hz: 0.2441 Samples per sec: 500.0 PSD Points: 2048 Overlap in %: 0 Temporal Resolution in sec: 4.096



No new data available Fri Aug 9 14:20:08 2002

Coordinate System: 121F05 Sensor ID: 121-f05 ; Axis: Sum of XYZ ; Windowing Method: Hanning

Cutoff Frequency in Hz: 100 df in Hz: 0.1221 Samples per sec: 250.0 PSD Points: 2048 Overlap in %: 0 Temporal Resolution in sec: 8.192



Nominal data

Coordinate System: 121F02 Sensor ID: 121-f02 ; Axis: Sum of XYZ ; Windowing Method: Hanning

Cutoff Frequency in Hz: 100 df in Hz: 0.1221 Samples per sec: 250.0 PSD Points: 2048 Overlap in %: 0 Temporal Resolution in sec: 8.192



Nominal operation

Coordinate System: 121F03 Sensor ID: 121-f03 ; Axis: Sum of XYZ ; Windowing Method: Hanning

Cutoff Frequency in Hz: 200 df in Hz: 0.2441 Samples per sec: 500.0 PSD Points: 2048 Overlap in %: 0 Temporal Resolution in sec: 4.096